


































SolidWorks Keyboard Shortcuts

Command	Shortcut(s)
 New..	Ctrl+N
 Open..	Ctrl+O
 Close..	Ctrl+W
 Save..	Ctrl+S
 Print..	Ctrl+P
Browse Recent Documents..	R
 Undo..	Ctrl+Z
 Redo..	Ctrl+Y
Repeat Last Command..	Enter
 Cut..	Ctrl+X
 Copy..	Ctrl+C
 Paste..	Ctrl+V
 Delete..	Delete
 Rebuild..	Ctrl+B
 Redraw..	Ctrl+R
 Orientation..	SpaceBar
 Zoom to Fit..	F
 Quick Snaps..	F3
 Full Screen..	F11
FeatureManager Tree Area..	F9
Toolbars..	F10
Task Pane..	Ctrl+F1
 Line..	L

 Front	Ctrl+1
 Back	Ctrl+2
 Left	Ctrl+3
 Right	Ctrl+4
 Top	Ctrl+5
 Bottom	Ctrl+6
 Isometric	Ctrl+7
 Normal To	Ctrl+8
Command option toggle	A
Expand/Collapse Tree	C
Collapse all Items.	Shift+C
 Filter Edges	E
Find/Replace	Ctrl+F
Next Edge	N
Force Regen	Ctrl+Q
Magnifying Glass	G
Shortcut Bar	S
 Filter Vertices	V
Hide/Show Display Pane.	F8
 Toggle Selection Filter Toolbar	F5
 Toggle Selection Filters	F6
 Spell Checker	F7
Scroll to FM tree top	Home
Scroll to FM tree bottom	End
 Filter Faces	X
Accept Edge	Y
Zoom Out	Z
Zoom In	Shift+Z
 Previous View	Ctrl+Shift+Z